

# TerrainLogic Conservation Practice Inspection Report

## South Field - Washington County, New York

|                     |                                      |
|---------------------|--------------------------------------|
| Practice            | South field 600-ft grassed waterway  |
| Practice ID         | prc_b4679c623f534ae79e75a07806662abe |
| Lifecycle status    | Built                                |
| As-built result     | PASS                                 |
| Routine inspections | 1                                    |

### As-built certification

| Inspection date | Inspector/certifier                     | Result | Max deviation (ft) | Tolerance (ft) | Reverse grade |
|-----------------|-----------------------------------------|--------|--------------------|----------------|---------------|
| 2026-08-10      | Jordan Ellis,<br>Engineering Technician | PASS   | 0.070              | 0.10           | No            |

### Routine inspection history

| Date       | Inspector/certifier | Result | Vegetation | Certified | Notes                                                                               |
|------------|---------------------|--------|------------|-----------|-------------------------------------------------------------------------------------|
| 2027-08-06 | Casey Faust         | PASS   | good       | Yes       | Dense grass cover, stable outlet, no headcut, and no sediment restriction observed. |

### Certification record

I certify that the recorded observations accurately describe the practice condition on the inspection date.

Inspector/certifier: \_\_\_\_\_ Date: \_\_\_\_\_

### Follow-up actions

Document repairs, reseeding, sediment removal, outlet stabilization, or additional survey required before the next certification.